


SAMBO INPUT SHAFT ASSEMBLY POSITIONS

Input / Output Shaft Rotation Options

Right Hand Input




① Right Hand Input
CW in- CW out is most standard
Assembly position "A"



② Right Hand Input
CW in- CCW out Assembly
position "B"

Left Hand Input



③ Left Hand Input
CW in- CW out is most standard
Assembly position "C"



④ Left Hand Input
CW in- CCW out Assembly
position "D"